

# QQQX2.E357067 - Electrically Isolated Semiconductor Devices - Component

*Note: We are enhancing our systems and you may notice duplicate entries/missing/outdated data. During this interim period, please contact our Customer Service at <https://www.ul.com/about/locations>.*

## Electrically Isolated Semiconductor Devices - Component

### CHIP INTEGRATION TECHNOLOGY CORP

E357067

2F-3 32Taiyuan St  
Zhubei  
Hsinchu Hsien, 302 Taiwan

Marking: Company name and model designation.

Note: For additional marking information, refer to the [Guide Information Page](#).

**Bridge rectifiers**, Model(s): KBPC, BR

**Bridge rectifiers**, Model(s): KBU/KBJ/RS/KBP/GBJ/GBP, DF/DB/WOB/DFS/DBS/MBS/MBM

**Bridge Rectifiers**, Model(s): KBL4005, KBL401, KBL402, KBL403, KBL404, KBL405, KBL406, KBL407, KBL408, KBL410, KBL6005, KBL601, KBL602, KBL603, KBL604, KBL605, KBL606, KBL607, KBL608, KBL610, KBP2005, KBP201, KBP202, KBP203, KBP204, KBP205, KBP206, KBP207, KBP208, KBP210, KBP3005, KBP301, KBP302, KBP303, KBP304, KBP305, KBP306, KBP307, KBP308, KBP310

**Bridge Rectifiers, Package Code 4KBJ**, Model(s): KBJ10005, KBJ1001, KBJ1002, KBJ1004, KBJ1006, KBJ1008, KBJ1010, KBJ4005, KBJ401, KBJ402, KBJ404, KBJ406, KBJ408, KBJ410, KBJ6005, KBJ601, KBJ602, KBJ604, KBJ606, KBJ608, KBJ610, KBJ8005, KBJ801, KBJ802, KBJ804, KBJ806, KBJ808, KBJ810

**Bridge Rectifiers, Package Code 6KBJ**, Model(s): GBJ10005, GBJ1001, GBJ1002, GBJ1004, GBJ1006, GBJ1008, GBJ1010, GBJ15005, GBJ1501, GBJ1502, GBJ1504, GBJ1506, GBJ1508, GBJ1510, GBJ20005, GBJ2001, GBJ2002, GBJ2004, GBJ2006, GBJ2008, GBJ2010, GBJ25005, GBJ2501, GBJ2502, GBJ2504, GBJ2506, GBJ2508, GBJ2510, GBJ35005, GBJ3501, GBJ3502, GBJ3504, GBJ3506, GBJ3508, GBJ3510, GBJ6005, GBJ601, GBJ602, GBJ604, GBJ606, GBJ608, GBJ610, GBJ8005, GBJ801, GBJ802, GBJ804, GBJ806, GBJ808, GBJ810

**Electrically Isolated Semiconductor Devices**, Model(s): S25VB10, S25VB100, S25VB20, S25VB40, S25VB60, S25VB80

**Electrically Isolated Semiconductor Devices, Bridge Rectifiers, Package Code GBU**, Model(s): GBU10005, GBU1001, GBU1002, GBU1004, GBU1006, GBU1008, GBU1010, GBU15005, GBU1501, GBU1502, GBU1504, GBU1506, GBU1508, GBU1510, GBU20005, GBU2001, GBU2002, GBU2004, GBU2006, GBU2008, GBU2010, GBU25005, GBU2501, GBU2502, GBU2504, GBU2506, GBU2508, GBU2510, GBU4005, GBU401, GBU402, GBU404, GBU406, GBU408, GBU410, GBU6005, GBU601, GBU602, GBU604, GBU606, GBU608, GBU610, GBU8005, GBU801, GBU802, GBU804, GBU806, GBU808, GBU810

**Electrically Isolated Semiconductor Devices, Package Code D3K**, Model(s): D2UB05, D2UB10, D2UB100, D2UB20, D2UB40, D2UB60, D2UB80, D3UB05, D3UB10, D3UB100, D3UB20, D3UB40, D3UB60, D3UB80, D4UB05, D4UB10, D4UB100, D4UB20, D4UB40, D4UB60, D4UB80

Last Updated on 2021-11-02

The appearance of a company's name or product in this database does not in itself assure that products so identified have been manufactured under UL's Follow-Up Service. Only those products bearing the UL Mark should be considered to be Certified and covered under UL's Follow-Up Service. Always look for the Mark on the product.

UL permits the reproduction of the material contained in the Online Certification Directory subject to the following conditions: 1. The Guide Information, Assemblies, Constructions, Designs, Systems, and/or Certifications (files) must be presented in their entirety and in a non-misleading manner, without any manipulation of the data (or drawings). 2. The statement "Reprinted from the Online Certifications Directory with permission from UL" must appear adjacent to the extracted material. In addition, the reprinted material must include a copyright notice in the following format: "© 2021 UL LLC"